

FIG. 1 is a perspective view of a helical spring 30. The spring has a top end 32 and a bottom end 31. An arrow points to the spring with the label "30 INSERT".

FIG. 3

NUT LOOSENING DIRECTION

NUT TIGHTENING DIRECTION

WELD FIXING

MALE SCREW PROJECTION SIDE

32

30

20 NUT

23

10 LOCKNUT

MALE SCREW INSERTION SIDE

22

CLAMPING SURFACE

FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9

